



Recommendation WG3.21.006

Replaces WG3.90.025

Notification of Apparent Operational Discrepancies

Subject Area: Coordination Procedures

Discrepancies in license information (e.g., incorrect coordinates) and operation (e.g., station not operating on licensed frequencies or station on air without authorization) are occasionally discovered by members of the industry during the frequency coordination process and/or field testing.

When an apparent discrepancy in another party's licensed information and/or station operation is discovered, the individual or organization discovering the discrepancy should send notification to the station's licensee. In addition, if the party discovering the discrepancy does so while under contract to a client whose facilities may be affected by the discrepancy, notification should also be made to the client.

Approved by WG3: 4/20/2021

Approved by NSMA Board: 5/26/2021

To Membership for Comment: 12/8/2021

Effective Date: 01/07/2022